



Product Change Notification

TE Connectivity

Product Change Notification: P-22-023179

PCN Date: 14-AUG-22

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

M12 CABLE ASSEMBLES ADD MANUFACTURING LOCATION

Description of Changes

Have an additional manufacturing location for M8M12 products. For following Part Numbers, at present, the manufacturing location is SIBAS, add a new manufacturing location HMO Mexico Industrial plant. SIBAS plant will continue supplying AP market. However SIBAS plant has already sold parts to other market as Americas!. HMO plant will sell to Americas market. However, if required, HMO plant at some point in the product life may sell to AP and EMEA besides America.

Reason for Changes:

Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about a transfer of tools and/or processes. The transfer is executed by following a strict transfer procedure, which guarantees no negative influence on quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location is under a certified quality management system according the standard industry requirements. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	07-NOV-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
TAD1453A201-001	NO						
TAD1453A201-002	NO						
TAD1453A201-003	NO						
TAD1453A201-020	NO						
TAD14541111-002	NO						
TAD14541111-003	NO						
TAD14541111-005	NO						
TAD14541111-020	NO						
TAD14741111-002	NO						
TAD14741111-005	NO						
TAD14741111-007	NO						
TAD14741111-300	NO						
TAD14841111-002	NO						
TAD14841111-005	NO						
TAD14845101-001	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
TAD14845101-002	NO						
TAD14845101-005	NO						
TAD14845101-020	NO						
TAX38125102-002	NO						
TAX38125102-004	NO						
TAX3812A202-002	NO						
TAX3812A202-004	NO						
TAX38225102-002	NO						
TAX38225102-004	NO						
TAX3822A202-002	NO						
TAX3822A202-004	NO						
TAX38721112-002	NO						
TAX38721112-004	NO						
TAX38725102-002	NO						
TAX38725102-004	NO						
TAX3872A202-002	NO						
TAX3872A202-004	NO						
TAX38821112-004	NO						
TAX38825102-002	NO						
TAX38825102-004	NO						
TAX3882A202-002	NO						
TAX3882A202-004	NO						
TCD1473A201-001	NO						
TCD1473A201-002	NO						
TCD1473A201-003	NO						
TCD1473A201-020	NO						
TCD14741111-001	NO						
TCD14741111-002	NO						
TCD14741111-003	NO						
TCD14741111-005	NO						
TCD14741111-020	NO						
TCD14745101-001	NO						
TCD14745101-002	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
TCD14745101-003	NO						
TCD14745101-020	NO						
TCX38721112-002	NO						
TCX38721112-004	NO						
TCX38725102-002	NO						
TCX38725102-004	NO						
TCX3872A202-002	NO						
TCX3872A202-004	NO						
TCX38825102-002	NO						