



Product Discontinuation Notice: AGF (GF1) Series Acceleration Sensors

PDN.PG24.7.9.2020

7.9.2020

Effective Date:	Immediate
Last Time Buy Date:	Immediate
Last Eligible Ship Date:	September 30, 2020
Discontinuation Details:	Panasonic has discontinued the AGF Series Acceleration Sensors for two reasons. The first reason is the supplier for the glass used for the Acceleration Sensor element is discontinuing the material. The second reason is for issues caused from an aging production facility for the Sensor element raising the maintenance costs.
Suggested Replacement:	
Affected Part Numbers:	See Attached.
Datasheets:	See Attached.
Notes:	

Affected Part Numbers

AGF10731

AGF10721

AGF10711

AGF11311

AGF10331

AGF10321